

Installation Contracts

Client	Location	Detail	Summary
Armored/Cash Vault Services	Tallahassee FL	INSTALL: CCTV system consisting of 14 interior and 2 exterior cameras, lenses and mounts, 1 Monitor, 1 DVR, and 1 quad.	
Armored/Cash Vault Services	Norcross GA	INSTALL: CCTV system consisting of 26 interior and 3 exterior cameras, lenses and mounts, 5 Monitors, 2 DVRs and 2 quads.	
Retail Mall	Newark DE	INSTALL: CCTV system consisting of 1 PTZ, 1 outside and 5 indoor cameras.	
Fire House Services	Odessa DE	INSTALL: 6 color camera CCTV system in main firehouse.	
Fire House Services	Odessa DE	INSTALL: 6 color camera CCTV system in aux. firehouse.	
Armored/Cash Vault Services	Ft. Myers FL	INSTALL: CCTV system consisting of 13 prewires, 25 interior and 3 exterior cameras, lenses and mounts, 4 Monitors, 3 DVR's, and 2 quads.	
Convenience Store	Wilmington DE	INSTALL: 4 camera Digital CCTV system with 1 monitor.	
Armored/Cash Vault Services	Baltimore MD	INSTALL: CCTV system consisting of 1 interior cameras and 4 exterior cameras, 1 monitors, 7 DVRs and 3 quads.	
Apartment Complex	Newark DE	INSTALL: CCTV system consisting of 8 operational and 6 dummy cameras.	

Armored/Cash Vault Services	Durham NC	INSTALL: Camera A-16 on the exterior of the building.	
Armored/Cash Vault Services	Elmhurst IL	INSTALL: CCTV system consisting of 12 prewires, 49 interior and 5 exterior cameras, lenses and mounts, 8 Monitors, 5 DVRs and 2 quads.	
Armored/Cash Vault Services	Oak Creek WI	INSTALL: CCTV system consisting of 23 interior and 5 exterior cameras, lenses and mounts, 1 Prewires, 5 Monitors, 3 DVRs, and 2 quads.	
Convenience Store	Avondale PA	INSTALL: 8 cameras, 3 monitoring fuel island, 3 monitoring customer space, 1 monitoring employee exit, 1 monitoring office. Install DVR, 21" monitor, power supply.	
Armored/Cash Vault Services	Jacksonville FL	INSTALL: 5 cameras and 1 multiplexer	
Armored/Cash Vault Services	St. Petersburg FL	INSTALL: 5 cameras and 1 multiplexer	
Armored/Cash Vault Services	Nashville TN	INSTALL: Six cameras.	
Armored/Cash Vault Services	Orlando FL	INSTALL: Eleven cameras and 1 DVR	
Armored/Cash Vault Services	Houston TX	INSTALL: CCTV system consisting of 19 interior and 2 exterior cameras, lenses and mounts, 5 monitors, 2 VCRs, 2 multiplexers, and 2 quads.	

Armored/Cash Vault Services	Grand Rapids MI	INSTALL: 16 camera CCTV system with 11 additional prewires. Four outside cameras, 2 quads and 4 monitors.	
Armored/Cash Vault Services	Dolton IL	INSTALL: CCTV system consisting of 13 interior and 2 exterior cameras, 1 quad and 2 monitors.	
Armored/Cash Vault Services	Miami FL	INSTALL: CCTV system consisting of 37 interior and 4 exterior cameras, lenses and mounts; 6 Monitors, 3 VCRs, 3 multiplexers, and 2 quads.	
Armored/Cash Vault Services	Flagstaff AZ	INSTALL: Single DVR system	
Furniture Retailer	Oaks PA	INSTALL: CCTV system consisting of 13 interior and 3 exterior cameras, lenses and mounts; 1 Monitor, and 1 DVR	
Armored/Cash Vault Services	Norfolk VA	INSTALL: CCTV system consisting of 3 interior and 2 exterior cameras, lenses and mounts, 5 Monitors, 2 VCRs, 2 multiplexers, and 2 quads.	
Armored/Cash Vault Services	Stratford CT	INSTALL: CCTV system consisting of 43 interior and 4 exterior cameras, lenses and mounts, 3 Monitors, 3 VCRs, 3 multiplexers, and 1 quad.	

Armored/Cash Vault Services	Tucson AZ	INSTALL: CCTV system consisting of 21 interior and 3 exterior cameras, lenses and mounts, 4 Monitors, 2 VCRs w/ alarms, 2 multiplexers, and 2 quads, 1 playback station.	
Armored/Cash Vault Services	Tallahassee FL	INSTALL: CCTV system consisting of 14 interior and 2 exterior Armored/Cash Vault Services	
Armored/Cash Vault Services	Bowie MD	INSTALL: CCTV system consisting of 36 interior and 4 exterior cameras, lenses and mounts; 5 Monitors, 4 VCRs, 4 mux, 2 quads, 16 prewires and 1 playback station.	
Convenience Store	Dover, DE	INSTALL: 7 camera CCTV system	
Armored/Cash Vault Services	Augusta GA	INSTALL: CCTV system consisting of 17 interior and 3 exterior cameras, lenses and mounts; 4 Monitors, 2 VCRs, 2 multiplexers and 2 quads.	
Armored/Cash Vault Services	Greensboro NC	INSTALL: CCTV System consisting of 41 interior and 2 exterior cameras, lenses and mounts; 5 monitors, 3 VCRs, 3 multiplexers and 2 quads.	
Armored/Cash Vault Services	Columbus GA	INSTALL: CCTV system consisting of 21 interior and 3 exterior cameras, lenses and mounts; 5 Monitors, 2 VCRs, 2 multiplexers, and 2 quads.	

Armored/Cash Vault Services	Macon GA	INSTALL: CCTV system consisting of 2 interior and 3 exterior cameras, lenses and mounts; 4 Monitors, 2 VCRs, 2 multiplexers, and 2 quads.	
Armored/Cash Vault Services	Nashville TN	INSTALL: CCTV system consisting of 37 interior and 4 exterior cameras, lenses and mounts; 6 monitors, 3 VCRs, 3 multiplexers, 2 quads, VCR alarm and playback station.	
Armored/Cash Vault Services	Durham NC	INSTALL: CCTV System consisting of 37 interior and 4 exterior cameras, lenses and mounts; 6 monitors, 3 VCRs, 3 multiplexers, 2 quads, VCR alarm and playback station.	
Armored/Cash Vault Services	Clarksburg MD	INSTALL: Two monitors mounted from ceiling in the managers office.	
Armored/Cash Vault Services	Cincinnati OH	INSTALL: CCTV system consisting of 7 interior cameras, lenses and mounts; 1 Monitor, 1 VCR, and 1 multiplexer.	
Armored/Cash Vault Services	Reading PA	INSTALL: Relocation and replacement of the dome camera on the roof.	
Armored/Cash Vault Services	Indianapolis IN	INSTALL: CCTV System consisting of 32 interior and 4 exterior cameras, lenses and mounts; 5 Monitors, 3 VCRs, 3 multiplexers, and 2 quads.	

Armored/Cash Vault Services	Livonia MI	INSTALL: 6 cameras connected to power supplies and muxes at existing pre-wires.	
Armored/Cash Vault Services	Denver CO	INSTALL: CCTV system consisting of 31 interior and 6 exterior cameras, lenses and mounts; 9 monitors, 3 VCRs, 3 multiplexers, and 2 quads.	
Armored/Cash Vault Services	West Palm Beach FL	INSTALL: CCTV system consisting of 15 interior and 3 exterior cameras, lenses and mounts; 4 monitors, 2 VCRs, 2 multiplexers, and 2 quads.	
Armored/Cash Vault Services	Colorado Springs CO	INSTALL: CCTV system consisting of 17 interior and 3 exterior cameras, lenses and mounts; 3 Monitors, 2 VCRs, 2 multiplexers, 2 quads, 1 prewire camera positions and 1 playback station.	
Armored/Cash Vault Services	Orlando FL	INSTALL: CCTV System consisting of 36 interior and 3 exterior color cameras, 5 2" monitors, 2 13" monitors, 4 VCRs, 1 Not recording alarm, 4 mux, 2 quad, 1 switch.	
Armored/Cash Vault Services	Jacksonville FL	INSTALL: CCTV System consisting of 38 interior and 3 exterior color cameras, 5 2" monitors, 2 13" monitors, 4 TLVCRs, 1 Not recording alarm, 4 mux, 2 quad, 1 switch.	

Armored/Cash Vault Services	Mc Allen TX	INSTALL: 7 cameras connected to head-end equipment	
Precious Metals Manufacturer	Fairfield NJ	INSTALL: 19" Rack System complete with monitor.	
Computer Retailer	Princeton NJ	INSTALL: 2 camera B&W system rmored/Cash Vault Services	
Armored/Cash Vault Services	Dallas TX	INSTALL: Relocate head-end equipment. Rewire 2 CCTV systems so that the networks are separated. Install alarm and configure the VCR's for master time sync.	
Armored/Cash Vault Services	Tallahassee FL	INSTALL: CCTV system consisting of 14 interior and 2 exterior Armored/Cash Vault Services	
Armored/Cash Vault Services	San Antonio TX	INSTALL: Relocate head-end equipment. Rewire 2 CCTV systems so that the networks are separated. Install alarm and configure the VCR's for master time sync.	
Armored/Cash Vault Services	Houston TX	INSTALL: Relocate head-end equipment. Rewire 2 CCTV systems so that the networks are separated. Install alarm and configure the VCR's for master time sync.	

Armored/Cash Vault Services	St. Petersburg FL	INSTALL: CCTV system consisting of 87 interior color cameras with fixed-iris lenses, 2 exterior color cameras with auto-iris lenses, 5 2-inch color monitors, 3 13-inch color monitors, 4 time-lapse VCRs, 1 VCR not recording alarm, 4 multiplexers, 2 quad and 2 switches.	
Computer Retailer	North Olmsted OH	INSTALL: 4 cameras, lenses, mounts, color duplex multiplexer, 1 monitor, and power supply.	
Armored/Cash Vault Services	Smyrna GA	INSTALL: 6 still cameras and connect to 2 existing multiplexers.	
Precious Metals Manufacturer	Fairfield NJ	INSTALL: 13 CCTV camera system in warehouse.	
Armored/Cash Vault Services	Cincinnati OH	INSTALL: Remove and replace 4 existing cameras. Install 3 new multiplexers and camera power supplies, 3 new VCRs in lockboxes, "not recording" alarm, switch, monitor and keyboard. Add 6 new cameras to system and relocate 1 existing quad and monitor.	

Armored/Cash Vault Services	Lexington KY	INSTALL: CCTV system consisting of 48 interior color cameras with fixed-iris lenses, 2 exterior color cameras with auto-iris lenses, 5 2-inch color monitors, 1 13-inch color monitor, 5 time-lapse VCRs, 1 VCR not recording alarm, 5 multiplexers, and 2 quads.	
Armored/Cash Vault Services	Denver CO	INSTALL: CCTV system consisting of 11 interior color cameras, 3 exterior color cameras, 2 2-inch color monitors, 2 time-lapse VCRs, 1 VCR not recording alarm, 1 multiplexer, and 1 quad.	
Armored/Cash Vault Services	Clarksburg MD	INSTALL: CCTV system consisting of 23 interior color cameras with fixed-iris lenses, 2 exterior color cameras with auto-iris lenses, 4 2-inch color monitors, 1 13-inch color monitor, 2 time-lapse VCRs, 1 VCR not recording alarm, 2 multiplexers, 2 quad and 1 A/B switch.	
Armored/Cash Vault Services	Edison NJ	INSTALL: 2 outside cameras and 1 monitor with a quad.	
Armored/Cash Vault Services	Edison NJ	INSTALL: 5 cameras.	
Armored/Cash Vault Services	Wilmington DE	INSTALL: 3 cameras, quad, and head end equipment.	
Armored/Cash Vault Services	Wilmington DE	INSTALL: 4 roof top cameras including all equipment mounts and adapters.	

Armored/Cash Vault Services	Las Vegas NV	INSTALL: 4 exterior cameras and lenses in enclosures with heater/blowers, add 1 monitor and connect to existing system.	
Armored/Cash Vault Services	Wilmington DE	INSTALL: 16 cameras and 1 mux and power supply.	
Armored/Cash Vault Services	Seattle WA	INSTALL: Change out all 16 cameras, mux, VCR and cabling.	
Candy Manufacturer	Philadelphia PA	INSTALL: 4 cameras, recorder and 2 monitors.	
Armored/Cash Vault Services	Austin TX	INSTALL: CCTV system consisting of 25 interior and 4 exterior cameras, lenses and mounts, 4 monitors, 3 VCRs, 2 multiplexers, 2 quads and 1 switcher.	